

**APPENDIX-L**  
**FORM 'S'**  
[See Rule 87 (5)]  
**Fire Audit Report Year 2023-2024**

Date: 21-08-2023

To

1. NAME: - PRESIDENT: SISTER ANN JOSE D/O. K. A. JOSEPH
2. ADDRESS: - PLOT No. - 423, ZONE - 25, WARD - 66, GRAM PIPROLI, GWALIOR (M.P.)


Sir,

**Sub: Submission Of Fire Audit Report of Building Name: - M/S NORTHERN PROVINCE OF CARMELITE SISTER OF ST. TERESA ST JOSEPH'S CONVENT SCHOOL and Address: - PLOT No. - 423, ZONE - 25, WARD - 66, GRAM PIPROLI, GWALIOR (M.P.)**


I TARUN GUPTA have inspected your building /premises on 21/08/2023 (Date) and checked all Fire Equipment's /installations and have completed the Fire Audit of the said Building/Premises for which Fire NOC No. 6000002366 dated 15-FEB-2019 issued by Fire Authority.

2. Details of fire system installed are as below:-


S. NO.	Name of System	Installed or not installed (as per requirements) (give comments)	Comments for working of system (attach details, if needed)
1.	ACCESS	FRONT - 12 M WIDE ROAD	-
2.	Wet Riser	NOT APPLICABLE	-
3	Down Comer	YES AVAILABLE HYDRANT POINT -12 NO.	-
4.	Hose Reel	YES INSTALL AT GROUND HOSPITAL FLOOR. TOTAL - 12 NO.	FOUND IN WORKING CONDITION.
5.	Automatic Sprinkler System	NOT APPLICABLE	-
6.	Yard Hydrant	NOT APPLICABLE	-

  
**Principal**  
St. Joseph's Convent School  
Piprolli




  
**Manager**  
St. Joseph's Convent School  
Piprolli

	Underground Tank with Draw off Connection	NOT APPLICABLE	
8.	Terrace Tanks	YES AVAILABLE 10000 LITTERS.	-
9.	Fire Pump	NOT APPLICABLE	-
10.	Terrace Pump	YES AVAILABLE PUMP - 450 LPM CAPACITY. MOTOR- 7.5 HP	FOUND IN WORKING CONDITION.
11.	First Aid Fire Fighting Appliances	YES AVAILABLE ABC TYPR 6 KG – 18 NO. CO2 GAS TYPE -1 NO. SEND BUCKET – 4 NO.	FOUND IN WORKING CONDITION.
12.	Pressurization System	NOT APPLICABLE	-
13.	Auto Detection System	NOT APPLICABLE	-
14.	Manual operated Electrical Fire Alarm System	YES AVAILABLE	FOUND IN WORKING CONDITION.
15.	P.A. System with talk back facility	NOT APPLICABLE	-
16	Emergency Light	NOT APPLICABLE	-
17.	Auto D.G. Set	AVAILABLE 10 KVA	-
18.	Illuminated Exit Sign	YES AVAILABLE AT EACH FLOOR.	
19.	Means of Escape	THREE STAIR CASE-1.2 M WIDE.	-
20.	Compartmentation	YES	-

  
Principal  
St. Joseph's Convent School  
Piproli



  
Manager  
St. Joseph's Convent School  
Piproli

21.	MCB/ELCB	YES	
22.	Fireman Switch in Lift	NOT APPLICABLE	
23.	Hose Boxes with Delivery Hose and Branch	YES AVAILABLE TOTAL - 12 NO.	
24.	Refuge Area	NOT APPLICABLE	
25.	Any other installation	NONE	

It is certified that the Installed Fire system as given above are in working condition and safe.

Date: 21-08-2023



Tarun Gupta

Fire Technology & Safety Engineer  
Authorized Fire Consultant By M P India

Signature

Name TARUN GUPTA  
(FIRE TECHNOLOGY AND SAFETY  
ENGINEER)

Principal  
St. Joseph's Convent School  
Piproli

Manager  
St. Joseph's Convent School  
Piproli